

# Vehicle Diagnostic Report

1999 RX300 1MZ-FE

1

Printed By: Default User(1)

09.06.2025 21:10:52

## Diagnostic Trouble Code Report

Engine and ECT(1 of 1)

DTC Monitors are Incomplete.

MIL: ON

Code	Description	Current	Pending	History	Permanent	Summary	Freeze Frame
P0171	System too Lean (Fuel Trim)	X	X	X		Icon B	Y
P1155	A/F Sensor Heater Circuit Malfunction (Bank 2 Sensor 1)	X	X	X		Icon B	Y