

Vehicle Diagnostic Report

2GRFXE

111

Printed By: Default User(1)

29.01.2023 17:55:25

Diagnostic Trouble Code Report Hybrid Control(1 of 1)

Code	Description	Current	Pending	History	Permanent	Summary	Freeze Frame
POA80	Replace Hybrid Battery Pack	X	X	X		Icon B	Y

Freeze Frame Data Report POA80(1 of 1)

Parameter	Value					Unit
	-3	-2	-1	0	1	
Battery Block Vol -V01	19,05	19,02	18,85	18,92	18,98	V
Battery Block Vol -V02	17,97	17,81	17,68	17,71	17,71	V
Battery Block Vol -V03	17,26	16,80	16,54	16,60	16,60	V
Battery Block Vol -V04	18,98	18,82	18,79	18,82	18,89	V
Battery Block Vol -V05	19,26	19,12	19,06	19,14	19,02	V
Battery Block Vol -V06	19,37	19,21	19,18	19,24	19,24	V
Battery Block Vol -V07	18,98	18,85	18,76	18,85	18,89	V
Battery Block Vol -V08	18,72	18,59	18,53	18,56	18,53	V
Battery Block Vol -V09	18,98	18,92	18,82	18,92	18,89	V
Battery Block Vol -V10	19,24	19,08	19,02	19,05	19,08	V
Battery Block Vol -V11	19,31	19,11	19,08	19,15	19,15	V
Battery Block Vol -V12	18,69	18,59	18,56	18,59	18,59	V
Battery Block Vol -V13	18,36	18,10	18,17	18,23	18,23	V
Battery Block Vol -V14	18,89	18,76	18,72	18,72	18,72	V
Battery Block Vol -V15	18,95	18,85	18,82	18,89	18,82	V